



Sea-Bird Electronics, Inc.
13431 NE 20th Street
Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866
service@seabird.com
www.seabird.com

SERVICE REPORT

RMA #: 00000100

Date: 16-SEP-2025

CUSTOMER INFORMATION

Name: UNIVERSITY OF RHODE ISLAND
Account : 40280802
Lynne Butler
lynnebutler@uri.edu
401 965 2143

PO Number: 0000226574
Notes: CONVERTED FROM PREVIOUS RMA:
1005523954

Bill To Address

UNIVERSITY OF RHODE ISLAND
75 LOWER COLLEGE RD, SUITE 1 - CARLOTTI ADMIN.
BLDG.
KINGSTON, RI, 02881
US

Ship To Address

UNIVERSITY OF RHODE ISLAND
20 RECEIVING RD. - GSO CENTRAL
RECEIVING/STOCKMAN
NARRAGANSETT, RI, 02882-1197
US

PRODUCTS SERVICED

Sales Order	Serial	Instrument	Description	Problems Found	Work Performed
321514359	3216020-0175	32.LEGACY	(LEGACY) SBE 32 Water Sampler Pylon (12/24/36)	The instrument was found to be flooded through the end cap. The actuator end cap, housing, bottom end cap, pylon assembly, and electronics require replacement.	Perform initial diagnostic evaluation. Replaced actuator endcap. Replaced actuator magnets (24). Replaced anodized housing. Replaced board stacks. Replaced connectors and connector endcap. Replaced the O-rings. Performed leak test. Performed fire latch test. Performed a hydrostatic pressure test. Replaced all Seabird label(s).

BILLABLE ITEMS

Instrument	Item	Item Description	Qty
3216020-0175:32.LEGACY	SBS-SVC-32P	COMPREHENSIVE SERVICE FOR SBE32 PYLON. (FRRF)	1
3216020-0175:32.LEGACY	801323	SBE32 24-PLACE COIL/ACT END CAP ASSY H900	1
3216020-0175:32.LEGACY	23670C	SBE32 TRIGGER HOUSING, HARDCOATED /20703HCC	1
3216020-0175:32.LEGACY	801915	SBE32 SER. INTERFACE ENDCAP ASSY (AL) MCBH	1

UNBILLABLE ITEMS

Instrument	Item	Item Description	Qty
3216020-0175:32.LEGACY	SBS-SVC-OTHER	SPECIFIC SERVICE REQUEST - CHECK DETAILED NOTES (FRRF)	1
3216020-0175:32.LEGACY	80754.1	SBE32 24-PLACE ELECTRONICS ASSY, TESTED	1